

Hygenic Thermopanel Installation at Tesco, Heswall 2001

Problem

Staff kitchen and bakery walls had serious problems with tiles detaching due to movement in building structure (built on stilts at side of estuary).

Geoff Ryan (Hygenic) assessed situation with Tesco personnel and maintenance contractors.

Solution

The solution was to install our PVC 10mm Thermopanel directly over existing tiles to seal existing surfaces and create new hygienic wall surfaces.

Works carried out at nights to staff kitchen and then to the bakery on another visit.

Result

Installation was a great success and a recent follow up survey revealed that the wall system is in excellent condition today (photos attached).